



INSPECTION REPORT

Page 1 of 6

SGS QUALITEST Industrie.
Division Inspection technique
Domaine de Corbeville Ouest
91400 ORSAY - France
Tel: +33 (1) 69336920

I.R No. : **IT/ORO/M/16.748**
SGS Ref N° **2016 OIT 00593**
SGS Contact : **Camille Lebreton**
Report Date : **October 10, 2016**

Project Name :	NI-PAKISTAN MODERNIZATION		
Project Ref. No :	/		
Customer:	ETIC	Supplier:	ETIC
Country :	FRANCE	Contact Person:	Nordine MESSAOUD
Executing SGS data:	SGS FRANCE	Place of inspection: ETIC	
SGS office:	ORSAY	3 rue du Moulin des arts 78550 HOUDAN - FRANCE	
Coordinator:	Camille Lebreton		

Inspection Details:			
Inspection Date :	October 10, 2016		
Work Order :	Purchase order ETIC n° 17946 dd.06.10.2016.		
Description of goods:	Elastomeric CR rubber profile for SBJ-5 expansion joints; quantity 9700 LM as per purchase order n°Etic/786/Fwo-22/06/B. New ETIC alloy aluminium special SBJ-5 expansion joints without holes for anchors tie bolt, quantity 700 LM as per purchase order n°Etic/786/Fwo-22/06.		
Intervention Required :	Quantity and samples.		
Attendees :	Mr. Eric BERNARD / ETIC		
Remarks:	None.		
Inspector Name:	Michel BERTH / SGS inspector	Date:	October 10,2016

SGS QUALITEST Industrie.
 Division Inspection technique
 Domaine de Corbeville Ouest
 91400 ORSAY - France
 Tel: +33 (1) 69336920

I.R No. : **IT/ORO/M/16.748**
 SGS Ref N° **2016 OIT 00593**
 SGS Contact : **Camille Lebreton**
 Report Date : **October 10, 2016**

1. Goods/Equipment detailed

Goods presented for inspection:

- Elastomeric CR rubber profile for SBJ-5 expansion joints, quantity 6600 meter. Partial of P/O n° Etic /786/Fwo-22/06/B
- New ETIC alloy aluminium special SBJ-5 expansion joints, quantity 715,5 meter. Totality of P/O n° Etic /786/Fwo-22/06

2. Reference Documents / Used documents

The following documents had been considered and used during the inspection:

- Purchase order n°Etic/786/Fwo-22/06 dd.27.06.2015
- Purchase order n°Etic/786/Fwo-22/06/B dd.27.06.2015

3. Instruments checklist

During the inspection, the following instrument calibration status has been checked:

No.	MEASURING INSTRUMENT DESCRIPTION (Including measuring range and equipment No.)	CALIBRATION STATUS	CERTIFICATE NO. (OPTIONAL)
1	None	/	/

4. Activities performed and Findings

4.1 Quantity

Materials presented to us were storage inside workshop of ETIC.

- Elastomeric CR rubber profile for SBJ-5 expansion joints.

22 pallets of 300 meter each have been presented to us.
6600 meter, Partial of P/O n° Etic /786/Fwo-22/06/B

- New ETIC alloy aluminium special SBJ-5 expansion joints.

4 pallets of 80 aluminum profil that is 320 pieces.

1 pallet of 84 aluminum profil that is 84 pieces.

1 pallet of 73 aluminum profil that is 73 pieces.

TOTAL = 477 pieces of 3 meters length that is 1431 meter presented to us.

1431:2 = 715,5 meter.

Totality of P/O n° Etic /786/Fwo-22/06

Quantity Results : Satisfactory

4.3 Samples

A sample of Elastomeric CR rubber profile for SBJ-5 and another sample for aluminium profile SBJ-5 were removed in our presence and packed in one cardboard box seal with SGS adhesive tape.

Samples Results :Satisfactory

SGS QUALITEST Industrie.
 Division Inspection technique
 Domaine de Corbeville Ouest
 91400 ORSAY - France
 Tel: +33 (1) 69336920

I.R No. : **IT/ORO/M/16.748**
 SGS Ref N° **2016 OIT 00593**
 SGS Contact : **Camille Lebreton**
 Report Date : **October 10, 2016**

TEST WITNESSING DISCLAIMER

In accordance with Client's instructions, the Company's involvement has been limited to witnessing/observing a third party's intervention(s) at the third party's laboratory/test house or other facilities and installations used for the intervention(s). The Company's sole responsibility was to be present at the time of the third party's intervention(s) to forward the results, or confirm the occurrence, of the intervention(s). The Company is not responsible for the condition or calibration of apparatus, instruments and measuring devices used, the analysis methods applied the qualifications, actions or omissions of the third party's personnel or the analysis results.

This document is issued by the Company under its General Conditions of Service accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx> Attention is drawn to the limitation of liability, Indemnification and jurisdiction issues defined therein. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

5. Conclusion

ON THE BASIS OF OUR FINDINGS, AT DATE AND PLACE OF OUR INTERVENTION, WE DECLARE THAT WE HAVE WELL PERFORMED THE SAMPLING ON GOODS AS PER CLIENT'S REQUEST.

THE ABOVE REFLECTS OUR FINDINGS AT TIME AND PLACE OF INSPECTION. THIS REPORT DOES NOT RELEASE BUYERS OR SELLERS FROM THEIR CONTRACTUAL RESPONSIBILITIES NOR DOES IT PREJUDICE BUYER'S RIGHT OF CLAIM TOWARD SELLERS/SUPPLIERS FOR COMPENSATION FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING OUR INSPECTION OR OCCURRING THEREAFTER.

SGS QUALITEST INDUSTRIE
Michel BERTH

SGS QUALITEST INDUSTRIE
Fausto CAMPOS


SGS Qualitest Industrie
Division Inspection Technique
 Domaine de Corbeville Ouest
 91400 ORSAY
 Tél. 01.69.33.69.20 - Fax 01.69.33.69.64

SGS Inspector

Capital Goods Department

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS QUALITEST Industrie.
 Division Inspection technique
 Domaine de Corbeville Ouest
 91400 ORSAY - France
 Tel: +33 (1) 69336920

I.R No. : **IT/ORO/M/16.748**
 SGS Ref N° **2016 OIT 00593**
 SGS Contact : **Camille Lebreton**
 Report Date : **October 10, 2016**

7. Pictures taken during inspection at ETIC Houdan workshop October 10, 2016




1. Pallets of aluminium profile




2. Pallets of aluminium profile




3. 80 profiles on 4 pallets



4. Section of aluminium profile



5. Dimension of sample before cutting



6. Dimension of sample after cutting

SGS QUALITEST Industrie.
 Division Inspection technique
 Domaine de Corbeville Ouest
 91400 ORSAY - France
 Tel: +33 (1) 69336920

I.R No. : **IT/ORO/M/16.748**
 SGS Ref N° **2016 OIT 00593**
 SGS Contact : **Camille Lebreton**
 Report Date : **October 10, 2016**



7. Pallets of elastomeric CR rubber profile SBJ-5



8. Pallets of elastomeric CR rubber profile



9. Pallets of elastomeric CR rubber profile



10. Pallets of elastomeric CR rubber profile



11. Pallets of elastomeric CR rubber profile



12. Pallet of elastomeric CR rubber profile

SGS QUALITEST Industrie.
 Division Inspection technique
 Domaine de Corbeville Ouest
 91400 ORSAY - France
 Tel: +33 (1) 69336920

I.R No. : **IT/ORO/M/16.748**
 SGS Ref N° **2016 OIT 00593**
 SGS Contact : **Camille Lebreton**
 Report Date : **October 10, 2016**



13. Dimension of sample before cutting



14. Dimension of sample after cutting



15. Samples of aluminium profile and elastomeric CR rubber profile SBJ-5 inside cardboard box



16. Packing of samples